


Attachment 5: Full Size Figures

Figure 1: East Bay Greenway Corridor Existing Conditions



Figure 2: East Bay Greenway Project Features



- 1 Close sidewalk gaps
 - 2 Separated pathways
 - 3 Landscaping and greening elements
 - 4 Pedestrian-scale lighting
 - 5 ADA - compliant ramps
 - 6 Raised medians and median refuges
 - 7 Narrower traffic lanes
 - 8 Pavement overlay/rehabilitation
 - 9 Enhanced crosswalks and crossing opportunities
 - 10 New and upgraded signals with pedestrian countdown, leading pedestrian interval and protected bike phases
- Additional features**
- Protected intersections
 - Bike-protected parking
 - Transit boarding islands

Figure 3: Project Vicinity Map




Figure 4: Project Collision Map






Figure 5: Corridor Crash Data Analysis

From 2015-2019, the project area saw 106 injury / fatal crashes involving pedestrians and cyclists, including 3 fatalities and 12 severe injuries.


Age of Pedestrian / Cyclist Victim



Common Causes of Pedestrian Crashes



Common Causes of Cyclist Crashes



NOTE: Light purple in the above figure indicates other causes of collision.

Figure 6: Rendering of East Bay Greenway from 2008 Community-Developed Concept Plan



Figure 7: Redlining Map of Project Area




Figure 8: Air Quality Map – Asthma Levels




Figure 9: Urban Tree Canopy in Project Corridor




Figure 10: Project Community Engagement



Figure 11: Access to Community Destinations




Figure 12: Proven Roadway Design Measures Include Separated Bike Lanes



Figure 13: Planned Mixed Use and Housing Developments in Project Corridor

